HO-959

8177 Hicks Road Waterloo Vicinity

Description:

The house at 8177 Hicks Road is located on a flat lot at the end of a long drive on the north side of Hicks Road, and is not visible from the street. It is situated near Waterloo in southeastern Howard County, Maryland. It is a one-story, three-bay by two-bay stuccoed structure with a gable roof that has asphalt shingles and a northeast-southwest ridge. The front faces southeast. There is an exterior parged chimney on the southwest gable end. The southeast elevation has a hollow-core center door that has three lights at the top, with a turned post in front of each light. There is a concrete porch with three concrete steps in front of the door. The south bay has a new one-over-one sash and the east bay has new, triple one-light casements. The southwest elevation has two new one-over-one sash on the first story, with no opening in the gable end. The northwest elevation has a shedroofed addition to the north that has beaded wood weatherboards and two one-light sash on the northwest and one on the southwest. The main block has a two-light sliding sash in the center bay. The northeast elevation has a cellar entrance in the east bay that is constructed with plywood and 2 by 4s, and it has a gable roof. There is a new one-overone sash in the north bay and a storm door in the addition. The gable end has a triangular vent. The interior has two rooms across the front, with an open stair well to the basement across the back wall of the east room. There are also rooms in the back corners, with a passage and bathroom set between them, and a pull-down stair to the attic. There is drywall on the walls, clamshell mouldings, and hollow-core doors. There are several makeshift sheds in poor condition across the rear of the lot.

#### Significance:

The house at 8177 Hicks Road is a Cape Cod, but without the dormer windows that are typical of this nationally popular house type. They began to be constructed in the U.S. in the 1930s but really became popular in the 1940s, as part of the post-war housing boom. The tax records indicated that the house was built in 1948, and there is nothing about the dwelling that would indicate that this date is inaccurate. The plan seems to be an open one, with a combination living room and dining room in the front, which the front door opens into, and another room in the front that was probably generally meant to be a bedroom. Across the back was the kitchen, off of the main living area, another bedroom, and a bathroom. The house is of little historical significance and is slated to be demolished in 2008 for redevelopment of the area.

# Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No.

HO-959

	roperty	(indicate prefer	red name)	1 31 3	y.	V., .	esto bro
historic							
other							
2. Location				any.			
street and number	8177 Hicks	Road				not for publi	cation
city, town	Waterloo				X	vicinity	
county	Howard						
3. Owner of	Property	(give names and ma	ailing addresses	of all owners	s)		
name	Kenneth &	Jacqueline Yates					
street and number	46 Poplar F	46 Poplar Point Road			telephone	410-22	24-7575
city, town	Edgewater		state	MD	zip code	21037-	1221
Contributing Determined I	Resource in Loc Eligible for the Na neligible for the HABS/HAER	ional Register District al Historic District ational Register/Marylan National Register/Maryla	400 C C C C C C C C C C C C C C C C C C				
Statement of the statem	ture Report of R	lesearch Nepolt					
Historic Struct							
Historic Struc	tion		in size				

7. Description	Inventory No. HO-959
Condition	
excellent	riorated
X good	3
excellent	

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

altered

fair

The house at 8177 Hicks Road is located on a flat lot at the end of a long drive on the north side of Hicks Road, and is not visible from the street. It is situated near Waterloo in southeastern Howard County, Maryland. It is a one-story, three-bay by two-bay stuccoed structure with a gable roof that has asphalt shingles and a northeast-southwest ridge. The front faces southeast. There is an exterior parged chimney on the southwest gable end. The southeast elevation has a hollow-core center door that has three lights at the top, with a turned post in front of each light. There is a concrete porch with three concrete steps in front of the door. The south bay has a new one-over-one sash and the east bay has new, triple one-light casements. The southwest elevation has two new one-over-one sash on the first story, with no opening in the gable end. The northwest elevation has a shed-roofed addition to the north that has beaded wood weatherboards and two one-light sash on the northwest and one on the southwest. The main block has a two-light sliding sash in the center bay. The northeast elevation has a cellar entrance in the east bay that is constructed with plywood and 2 by 4s, and it has a gable roof. There is a new one-over-one sash in the north bay and a storm door in the addition. The gable end has a triangular vent. The interior has two rooms across the front, with an open stair well to the basement across the back wall of the east room. There are also rooms in the back corners, with a passage and bathroom set between them, and a pull-down stair to the attic. There is drywall on the walls, clamshell mouldings, and hollow-core doors. There are several makeshift sheds in poor condition across the rear of the lot.

8. Significance			Inventory No.	Inventory No. HO-959		
Period	Areas of Signif	icance Check and jus	tify below			
1600-1699 1700-1799 1800-1899 2000-	agriculture archeology X architecture art commerce communica community conservatio	entertainment recreation tions ethnic heritage planning exploration/	law	performing arts philospohy politics/government religion science social history transportation other:		
Specific dat	es N/A		Architect/Builder N	/A		
Construction	n dates c. 194	18				
Evaluation for	or:					
	lational Register	Ma	aryland Register	X not evaluated		

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance reports, complete evaluation on a DOE Form - see manual.)

The house at 8177 Hicks Road is a Cape Cod, but without the dormer windows that are typical of this nationally popular house type. They began to be constructed in the U.S. in the 1930s but really became popular in the 1940s, as part of the post-war housing boom. The tax records indicated that the house was built in 1948, and there is nothing about the dwelling that would indicate that this date is inaccurate. The plan seems to be an open one, with a combination living room and dining room in the front, which the front door opens into, and another room in the front that was probably generally meant to be a bedroom. Across the back was the kitchen, off of the main living area, another bedroom, and a bathroom. The house is of little historical significance and is slated to be demolished in 2008 for redevelopment of the area.

# 9. Major Bibliographical References

Inventory No.

in societie

HO-959

12(1)

See continuation sheet. footnotes

## 10. Geographical Data

Acreage of surveyed property 13,677 sq. ft.

Acreage of historical setting 13,6

13,677 sq. ft.

Quadrangle name

Savage

Quadrangle scale

1:24000

Verbal boundary description and justification

The boundaries consist of all of the property on tax map 43, p. 493, which encompasses all of the historic structures.

## 11. Form Prepared By

name/title	Ken Short				
organization	Howard County Dept. of Planning & Zoning	date	10/31/2008		
street and number	3430 Courthouse Drive	telephone	410-313-4335		
city or town	Ellicott City	state MD z	rip code 21043		

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

DHCD/DHCP


100 Community Place Crownsville MD 21032

410-514-7600

demolished c. 2008







HO-959 8177 Hicks Road Savage Quad Waterloo vicinity

8177 Hicks Road Howard County, Maryland Ken Short, photographer

Photo Log

Nikon D-70 camera HP Premium Plus paper HP Gray Photo print cartridge

HO-0958\_20081017\_01 House, southwest & southeast elevations

HO-0958\_20081017\_02 House, northeast & northwest elevations



Ho-959 8177 Klicks Pl Howard Co MD Ken Start, plotographer

House Southwest & Southeast elevations



HO-959 8177 Hecks Rd Howard Co MD Ken Short, photographer 10-17-08 House, northeast + northwest elevations 2 of 2